

Firmware Change History for TM-P80 (Manualcutter model)

Version	Category	Detail
1.21 ESC/POS	Function change	Improved the print quality
	Bug fix	Fixed a bug that BM settings saved by the "GS (M "command are invalidated by the buffer clear command from TM utility
		Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control
1.22 ESC/POS	Bug fix	Fixed a bug that the print density is low.