

Firmware Change History for TM-T70II (180 dpi model)

Version	Category	Detail
5.05 ESC/POS	Function change	Applied countermeasures to prevent missing dots caused by Over energy.
	Bug fix	Fixed a bug that the printer is printing mangled QR codes or graphics when the receipt exceeds a certain size.
5.11 ESC/POS	Function change	Shortened the emission time of the paper real-end detector to prevent its deterioration.
5.12 ESC/POS	Bug fix	Fixed a bug that prevented the printer receiving the third USB event and subsequent events if the printer had received two USB events at the same time for the printer connected to the host PC via USB.
		Fixed a bug that might cause the CPU execution error when the paper ends during printing.