

EPSON OPOS ADK

| Model | Ver. 2.40E SP1 |
|--------------|----------------|
| D101II/D102 | Yes |
| D105/D106 | Yes |
| D110 | Yes |
| D202II/D203 | Yes |
| D205/D206 | Yes |
| D210 | Yes |
| D500 | Yes |
| IM400 Series | No |
| IM505/IM515 | Yes |
| IMX40 | No |
| IR300/IM300 | Yes |
| IR310/IM310 | Yes |
| IR320/IM320 | Yes |
| IR700 | Yes New!! |
| SR600 | Yes |
| MR800 | No |
| H5000 | No |
| H5000II | Yes |
| H6000 | Yes |
| H6000II | Yes |
| H6000III | No |
| J2000/J2100 | Yes |
| J7000/J7100 | Yes |
| J7500/J7600 | Yes |
| J8000 | Yes |
| T80 | No |
| T85 | No |
| T88 | No |
| T88II | Yes |
| T88III | Yes |
| T90 | Yes |
| P60 | Yes |
| L60II | Yes |
| L90 | Yes |
| L90 Peeler | Yes |
| U200 Series | Yes |
| U210 | Yes |
| U220 | Yes |
| U230 | Yes |
| U300 | Yes |
| U325 | Yes |
| U375 | Yes |
| U675 | Yes |
| U925 | No |
| U950 | Yes |
| RPU420 | Yes |
| U295 | Yes |
| U590 | Yes |

There are models that are not handled in the region.